

November 15, 2013

INVITATION TO TENDER "ITT" NO. PS20130871
BODEL CONSERVATORY ROOF PANEL REPAIRS

ADDENDUM NO. 1

RE: APPENDIX 3 - SPECIFICATIONS

PLEASE ADD:

Add the following paragraph to Section 08800, 1.3 Performance Requirements:

".6 Gasket thicknesses to ensure the appropriate compression of gaskets. Installed gaskets to be compressed 25 to 40% to form weathertight seal, in accordance to Glazing Association of North American (GANA) Glazing Manual."

This addendum must be completed, and attached to your Proposal form.

If you have already submitted your Tender, this addendum shall be submitted to the Purchasing Services Office, City of Vancouver, 453 West 12th Avenue, Vancouver, British Columbia, Canada, V5Y 1V4, (Courier Delivery and Drop off is at the Information Desk, Main Floor Rotunda of the same address), prior to the Closing Time: 3:00:00 pm Local Vancouver, BC Time, in an envelope clearly marked "Addendum No.1 to Invitation to Tender No. PS20130871:Bodel Conservatory Roof Panel Repairs. before the closing time of 3:00 p.m., November 19, 2013.

NAME OF VENDOR

SIGNATURE OF AUTHORIZED SIGNATORY

DATE