

**INVITATION TO TENDER "ITT" NO. PS20210042
CONSTRUCTION SERVICES FOR 2021 GAS SYSTEM EXPANSION AND UPGRADES -
VANCOUVER LANDFILL**

QUESTIONS AND ANSWERS NO. 3

ISSUED ON MARCH 17, 2021

Q1

There appears to be a similar QTY issue with the cover penetration seals per below:

Item	Description	UoM	SOQ Estimated QTY	Drawing Takeoff Quantity	QTY Variance
2.39 & 4.16	Cover Penetration Seal	EA	80	41	-39
3.07	Interim Cover Penetration Seal	EA	5	5	0

Please review and advise if any changes will be made to the SOQ, or clarify where the additional cover penetration seals are located.

A1

The additional cover penetration seals are located on the Well Head Manifold Assemblies shown on Drawings 226, 233, and 236 per Amendment No. 1

Item	Description	Qty	Unit	Dwg	Count	
2.39	Cover Penetration Seal	59	ea	206	2	Type 1 P03-V120 & P03-V121
				207	3	Type 1 P03-V119 & P03-V122 & P03-V123
				208	2	Type 2 P01-V038 & P01-V042
				210	8	Type 3 Man "F"
				210	8	Type 4 Man "F"
				210	8	Type 3 Man "G"
				210	8	Type 4 Man "G"
				210	10	Type 3 Man "G"
				210	10	Type 4 Man "G"
				3.07	Interim Cover Penetration Seal	5
210	2	Interim P05-TV01 & TV02				
4.16	Cover Penetration Seal	16	ea	210	8	Type 3 Man "E"
				210	8	Type 4 Man "E"

See Schedule "A" - Schedule of Quantities and Prices, issued with Amendment No. 3.