

INVITATION TO TENDER "ITT" No. PS20200272 CONCRETE REPAIR - VANCOUVER SOUTH TRANSFER STATION

QUESTIONS AND ANSWERS NO. 3

ISSUED ON NOVEMBER 10, 2020

Q1	Drawing TLO 119 - when it says to grind to good concrete, is there an expected depth that we can abase our estimate on that we would have to go down to find sound concrete (ie. 50mm or 200mm)
A1	Most of the old sacrificial asphalt is expected to be worn off and hence likely less than 50mm on average.
Q2	In the concrete repair section 3.3 should this section include concrete as part of the repair items or should all concrete used be under 3.3 supply and install? (should we put all the cost for concrete in the supply and install section and none in the "tipping floor repair as per 218" and "tipping floor repairs middle as per drawing 219"
A2	Amendment No. 4 will remove the line item within Part C - Form of Tender - Schedule "A" - Quantities and Prices that says "Supply & install concrete in the middle of the pit according to drawing TLO219, 115 m^3 of concrete" because that work is already captured under the line item "Pit floor repairs middle as per drawing TLO219" and hence it is redundant.

