

INVITATION TO TENDER NO. PS20210298

CONTRACTOR FOR TEMPLETON TRACK RENEWAL

QUESTIONS AND ANSWERS NO. 1

ISSUED ON MAY 14, 2021

Q1	What is the thickness of the asphalt on the existing track?
A1	The available as-built documentation for this area does not indicate asphalt thickness.
Q2	What is the thickness of the rubber on the existing track?
A2	Thickness varies due to extensive wear on this surfacing. Approximate depths can be identified by visual inspection.
Q3	Are you able to provide the thickness of the existing asphalt that runs between the track and the Templeton Park Pool?
A3	The available as-built documentation for this area does not indicate asphalt thickness.
Q4	How thick is the existing long jump asphalt?
A4	The available as-built documentation for this area does not indicate asphalt thickness.

INVITATION TO TENDER NO. PS20210298

CONTRACTOR FOR TEMPLETON TRACK RENEWAL

QUESTIONS AND ANSWERS NO. 1

Q5	Does the playground need to be kept open to the public during track construction?
A5	We currently anticipate closing the playground during construction.